

HR 4801

To direct the Administrator of the Federal Aviation Administration to issue an order regarding secondary cockpit barriers.

Congress: 108 (2003–2005, Ended)

Chamber: House

Policy Area: Transportation and Public Works

Introduced: Jul 9, 2004

Current Status: Referred to the Subcommittee on Aviation.

Latest Action: Referred to the Subcommittee on Aviation. (Jul 12, 2004)

Official Text: <https://www.congress.gov/bill/108th-congress/house-bill/4801>

Sponsor

Name: Rep. Israel, Steve [D-NY-2]

Party: Democratic • **State:** NY • **Chamber:** House

Cosponsors

No cosponsors are listed for this bill.

Committee Activity

Committee	Chamber	Activity	Date
Transportation and Infrastructure Committee	House	Referred to	Jul 12, 2004

Subjects & Policy Tags

Policy Area:

Transportation and Public Works

Related Bills

No related bills are listed.

Summary (as of Jul 9, 2004)

Directs the Administrator of the Federal Aviation Administration to issue an order requiring: (1) the installation of secondary cockpit barriers preventing access to the flight deck of commercial aircraft; and (2) that such secondary barriers remain locked while the aircraft is in flight and the cockpit door separating the flight deck and the passenger area is open.

Actions Timeline

- **Jul 12, 2004:** Referred to the Subcommittee on Aviation.
- **Jul 9, 2004:** Introduced in House
- **Jul 9, 2004:** Introduced in House
- **Jul 9, 2004:** Referred to the House Committee on Transportation and Infrastructure.